


# Customer Sales Order

	11/12/2013	<b>EMS Redline Sprinter Type II "SE"</b> <i>Customer</i>	<b>1264</b>
	707-546-1070		
Steve De La Montanya 143 Meadow Place Windsor, CA 95492			

Itemnumber	Description
------------	-------------

## 10 - BASE SECTION

10.

10. 1	Prep van and misc	
10. 33	(2013 Mid Year) Sprinter "SE" Type II Base Conversion	<b>\$33,659</b>
10. 62	(2013) Mercedes Benz Sprinter 2500 Van Chassis 144" (Content of chassis and cost subject to change due to availability)	<b>\$38,635</b>

STANDARD FEATURES

- 147 Arctic White Paint
- VH5 Lima Black Upholstery & Trim
- 3.0 Liter V6 Turbo Diesel Engine
- 188 hp @ 3,800 RPM
- 325 lb-ft of torque @ 1,400 - 2,400 rpm
- 5-Speed Automatic Transmission
- 220 Amp Alternator
- Front Stabilizer Bar
- Tire Pressure Monitoring System
- Shelf Above Windshield
- Adaptive Electronic Stability Program (ESP)
- Power Windows
- Remote Central Locking
- 4-Wheel Anti-Lock Braking System (ABS)
- Brake Assist (BAS)

OPTIONAL EQUIPMENT & PACKAGES

- High Roof
- (2) Additional Keys
- Daytime Running Lights
- Bracket For Aux A/C Compressor
- Alloy Wheels
- Seat Belt Orange, Driver and Passenger
- V01 Premium Package
- Window Package II
- RPM Governor Package
- Auxliary Battery With Disconnect

## 20 - PRE TAX

20.

20. 1	Document Processing Fees	<b>\$50</b>
-------	--------------------------	-------------

30.



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber Description

40 - COMPLIANCE

40.

40. 1 Add KKK labels, attach to oxygen compartment and behind drivers seat.

51.

200 - INTERIOR CABINETS - STANDARD

A.

A. 1 Cabinet street side, rear, folding stretcher storage w/ 1" black strap & quick connect clip, removable lower shelf for access to cot fastener bolts & optional batteries.

A. 2 Cabinet street side, center, (2) storage cabinets w/ adjustable shelves, and sliding polycarbonate doors.

A. 3 Cabinet street side, "Action Wall", (1) upper storage cabinet w/ sliding polycarbonate doors, (1) lower storage cabinet w/ sliding polycarbonate doors, (1) lower hinged wood door w/ PVC banded edges w/ (2) vents & non-locking latch for Inverter access.

A. 4 Cabinet street side, forward, (2) storage cabinets w/ sliding polycarbonate doors, (1) open storage area to house (3) latex glove boxes.  
NOTE: (3) boxes of latex gloves included.

A. 5 Cabinet street side upper, (2) storage cabinets w/ polycarbonate doors, (1) exhaust vent intake grille, (1) locking drug cabinet w/ hinged wood door w/ PVC banded edges w/ 7/8 keyed lock. A/C plenum located above storage cabinets w/ (5) air output rotating louvers.

A. 6 Street side solid partition with window opening & transverse oxygen cabinet below, w/ (1) oxygen access opening on cabinet face w/ hinged polycarbonate door w/ finger hole.

A. 7 Curb side partition & transverse oxygen cabinet below, oxygen cabinet will accept "H" or "M" tank, (1) oxygen access opening on cabinet face w/ hinged polycarbonate door, (1) hinged wood door with non-locking latch and PVC banded edges @ side for oxygen tank access w/ stainless steel protective sill. (2) ALS adjustable (powder coated) metal shelves 21"x12" w/ 1" upper lip (trim lock added to lip), fasten to aluminum uni-strut recessed into partition. Add a 1" aluminum lip (trim lock added to lip) bordering the outside edges to the top of the transverse oxygen cabinet below metal shelves. Supply (4) 1 inch black straps with quick connect clips, (1) per metal shelf & (2) on top of transverse oxygen cabinet.

A. 8 Upper partition cabinet w/ A/C platform, A/C evaporator housed insde. (A/C platform to have 110 & 12volt hole cut outs) Patient compartment face to have (1) storage cabinet w/ self closing hinged polycarbonate door w/ black pull ring latch, (LEADER "SE" engraved in polycarbonate) Cab side to have a hinged wood door w/ locking latch for access to electrical compartment, and (1) Gibraltar A/C intake vent.



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber	Description
A. 9	Squad Bench, curb side wall, slanted storage for oversized backboards, constructed of 16 gage aluminum. (2) hinged seat lids w/ gas cylinder hold open devices & rubber flex draw hold down latches per lid. (1) horizontal back rest and (1) horizontal head rest. Seat belt cut outs - (2) patient retractable lap belts, and (2) attendant retractable lap belts. Forward location for top drop (Kendall 5qt) sharps container & trash container, a single hinged red polycarbonate lid for trash container only w/ aluminum edge handle. NOTE: (1 Sharps and 1 Trash container included)
A. 10	Curb side, overhead cabinet above squad bench, (2) storage areas w/ sliding polycarbonate doors.
A. 11	Action wall panel, wood panel laminated with black formica with oxygen & electrical cut outs.
<b>200 - INTERIOR CABINETS - OPTIONS</b>	
A. 200	
A. 201	"SE" Center Console w/ (2) cup holders and map storage. <span style="float: right;"><b>\$264</b></span>
<b>300 - INTERIOR TRIM AND COLOR - STANDARD</b>	
B.	
B. 1	Floor color/material - ( Non Covered) trimed with aluminum cove molding along edges, Anti-Microbial, Lonseal - Lonfloor Flecks #500 Onyx.
B. 2	Headbumpers/Fillers upholstery color/material - Black Doeskin #DOS4849 w/ 1/4" closed cell foam.
B. 3	Seat Cushions / Back Rest / Head Rest, upholstery color/material - Black Doeskin #DOS4849 (seamless) w/ 2" foam for seat cushions & back rest, and 1 1/2" foam for head rest.
B. 4	Attendant seat, EVS #17803E Black high back (seamless) attendant seat w/ 3 point restraint, w/ Leader stamped into seat, w/ reinforced pedestal base #CBPED w/out track, seat is in a fixed location.
B. 5	Laminate color, exterior (upper) matte, Light Grey - D 355 / interior of cabinets to match exterior color.
B. 6	Laminate color, exterior (lower) matte, Dark Grey - 10592 / interior of cabinets to match exterior color. Stretcher cabinet to be laminated with Dakota Ridge.
B. 7	Headliner -- cab / patient compartment .- Cab to remain OEM, patient compartment to use 1/4" laminated masonite with White Matte finish.
B. 8	Polycarbonate color .240, Clear
B. 9	Polycarbonate sliding doors, retain handles on doors and provide holes for cable ties.
B. 10	Patient compartment door panels, OEM
B. 11	Insulation, foil backed bubble astro-cooler walls and roof areas.



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber Description

300 - INTERIOR TRIM AND COLOR - OPTIONS

B. 300

B. 301 Rubber Mat Set (3), rubber mat inserts for (3) ALS shelf areas. \$75

400 - WARNING DEVICES - STANDARD

C.

C. 1 Light bar front, Code III LED/HALOGEN, #LEDX2100/2158A, Red/Clear lense, steady Red in center section. (2) Cast Product aluminum mounting brackets.

C. 2 Warning lights rear, Code III 85A and 85R LED , (2) Red inboard, (2) Amber outboard. ( lights only)

C. 3 Warning lights side, Code III 85R LED Red, (4) total.(2) per side ( lights only).

C. 4 Warning lights grille, (2) Code III LED #TRX6R w/ chrome bezel, Red flashing, mounted on Leader style metal bracket located in upper corners of gille.

C. 5 Warning lights patient compartment, (2) Code III LED #TRX6R w/ chrome bezel, mounted in patient compartment on upper cabinet at rear, driver and passenger side. To activate w / PRI--SEC switch ( both positions ) and only when the rear patient compartment entry doors are open.

C. 6 Scene lights side , Code III # 41 Halogen w / 26 degree, (4) total. (2) per side ( lights only ).

C. 7 Scene lights rear, Code III # 41 Halogen 26 degree, mounted on interior headliner above rear doors.

C. 8 Clearance lights, Whelen LED (4) total. (2) front Amber, (2) rear Red, mounted in Cast Product light housing:

C. 9 Light housings aluminum, side, (4) total. (2) per side. Three light combo: Warning light 900 series / Scene light 700 series / Clearance light.

C. 10 Light housings, aluminum, rear, (2) driver--passenger , (2) light combo: Warning light 900 series / Warning light 900 series.

C. 11 Siren speaker, (2) 100 Watt CPI, driver and passenger sides, mounted through bumper.

C. 12 Back-up alarm, rear mounted, 97 decibel with auto reset, console defeat switch.

400 - WARNING DEVICES - OPTIONS

C. 400

C. 401 Intersection lights FRONT fenders, (2) 45BZR Code III LED (Red) flashing w/ chrome flange. \$316

Note: K Spec

500 - ELECTRICAL CONTROL CENTER - STANDARD



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber Description

D.

D. 1 Overhead console fiberglass, (201 Head Impact Compliant) w/ electrical components, circuit board.

D. 2 Switch panel overhead, ("SE" Model w/ Black Finish) backlit, with cutouts, (12) legends included.

D. 3 Siren electronic, w/ remote amp, mounted in overhead console, Whelen 295HFSA7 Ca. Spec. (high low deleted) flush mount bezel, dual tone, 100 watt output, w/ removable mic, hands free, horn ring control.

D. 4 Indicator lamp Green, MASTER ON, C.H. LED pilot light.

D. 5 Switch, PRI. SEC., center off, primary controls all emergency lights, secondary controls rear ambulance (outboard) warning lights only, panel mounted C.H. LED switch, lit Red/Amber.

D. 6 Switch, BACK-UP ALARM, C.H., non-lit momentary.

D. 7 Switch, LEFT FLOOD, C.H. LED, lit White.

D. 8 Switch, RIGHT FLOOD, C.H. LED, lit White.

D. 9 Switch, PATIENT DOME, 3-way, C.H. LED, lit Amber.

D. 10 Switch, PATIENT HEAT/AC, 3-way, C.H. LED, lit Blue.

D. 11 Switch, MODULE DISCONNECT, C.H. LED, lit Green.

D. 12 Map light, Hella 19", mounted on OEM dash, passenger side.

D. 13 Two-way radio power, Positive - Negative - Ignition, with terminal strip, located on partition wall behind drivers seat in cab.  
NOTE: If optional center console is selected re-locate terminal strip to center console.

500 - ELECTRICAL CONTROL CENTER - OPTIONS

D. 500

D. 502 12 Volt wiring Positive-Negative pair, terminate behind drivers seat w/ 3 feet coil.

\$54

600 - ELECTRICAL PATIENT COMPARTMENT - STANDARD

E.

E. 1 Dome lamps, ceiling, (5) Flush mount Halogen High - Low, door jam switch and switch panel activated, door jam switch to activate all (5) in low intensity only, action wall switch activates all in high-low intensity.

E. 2 Electrical outlet 12 volt, (2) , rear action wall, and ALS cabinet, cigarette style.



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber	Description
E. 3	Electrical outlet (2) 120V, ALS cabinet, action wall, with pilot lights, mounted on grey plastic housings, wired to shore power.
E. 4	Switch plate rear, (10) position Black Santex (switch plate only), back lit (includes legends)
E. 5	Switch, DOME, 3-way, C.H. LED, lit Amber.
E. 6	Switch, DOME HI-LO, C.H. (non lit)
E. 7	Switch, EXHAUST, C.H. LED, lit Amber.
E. 8	Switch, ELECT SUCTION, C.H. LED, lit Amber.
E. 9	Switch, PATIENT HEAT A/C, 3-way, C.H. LED, lit Blue.
E. 10	Switch, A/C, FAN HI-LO, C.H, (non-lit)
E. 11	Switch, A/C, HEAT-COOL, C.H. lit Red - Blue
E. 12	Shore power, 120V, 15 amp, behind driver door, Hubbell cast cover, wired to 110V outlets in patient compartment.
E. 13	Restocking light timer, passenger rear filler, 5 minute, controls drivers side dome lights.
E. 14	Step Well Light LED, located in side door step well, door switch activated. (Grote)
E. 15	Inverter Pre-Wire, Includes 12 volt Pos-Neg with Anderson quick disconnect connector, terminating inside inverter compartment. (Does not include remote panel or rocker switch)

**600 - ELECTRICAL PATIENT COMPARTMENT - OPTIONS**

E. 600

E. 605	Battery Charger, IOTA 45 amp (connected to shoreline)	<b>\$262</b>
<b>Note: K Spec</b>		

**700 - ELECTRICAL AND MECHANICAL - STANDARD**

F.

F. 1	Air conditioning / Heater, patient compartment, control air, additional compressor, auxiliary (3) fan condenser kit, mounted under vehicle driver side (mid - section). Patient system is independent of OEM cab system.
F. 2	Power Exhaust vent, left rear, Cast Products exterior cover, interior louver round
F. 3	Batteries (2) Total, OEM batteries to remain in original location.
F. 4	Shut Down Timer, with 5 min. delay activated via ignition switch.
F. 5	Wiring loom, Leader fabricated, hi temp SXL, color coded, number coded and function labeled, with split loom wire protection



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber Description

F. 6 Antenna wiring RG58AU (2), located in patient compartment ceiling behind two forward dome lights, terminates behind drivers seat in front cab.

F. 700

800 - OXYGEN SYSTEM - STANDARD

G.

G. 1 Aspirator, action wall area, SSCOR 22000, flush mount panel and gauge.

G. 2 Vacuum pump, 12V, w/vent tube to exterior.

G. 3 Oxygen system, (2) outlets Amico Ohio style quick release, mounted on grey plastic housings in action wall panel.

G. 4 Oxygen bottle rack, transverse mount, Leader Brand, Must Specify "M" or "H" tank. (Leader Brand has the capability of stacking "M" size, one on top of the other)

800 - OXYGEN SYSTEM - OPTIONS

G. 800

G. 804 Oxygen regulator, preset 50 psi. \$82

Note: K Spec

G. 820 Oxygen wrench, cable to wall by large bottle. \$28

Note: K Spec

900 - HARDWARE -STANDARD

H.

H. 1 Seat belts, patient compartment, (4) sets of lap belts, (2) for squad bench attendants, (2) for squad bench patient.

H. 2 I.V. hardware, wall mount, (2), Chrome spring loaded clip type, surface mounted, (see print for location)

H. 3 (2) Pull handles, patient compartment interior rear doors.

H. 4 Ceiling grab rail, center mounted, stainless steel, 64 inch length, satin finish.

H. 5 Door sills (2) side & rear, bright stainless steel, with ramp edge at rear.

H. 6 Rear bumper step, (flip up) grip strut grating, grey powder coated.

H. 7 Hardware plates ceiling area, cargo net, grab bar, cabinetry

H. 8 Metal "C" shape safety strap for OEM door hold open, (passenger side only)

900 - HARDWARE - OPTIONS



11/12/2013

EMS Redline Sprinter Type II "SE"

Customer

1264

Steve De La Montanya  
143 Meadow Place  
Windsor, CA 95492

707-546-1070

720 Portal Street  
Cotati, CA 94931  
Justin Calaway

707.975.3926

VIN Number

Parent Job 1264

Itemnumber	Description	
H. 900		
H. 901	Cargo Net, located @ head end of squad bench, Ancra fasteners, ratchet, 1 1/2" black webbing.	\$319
H. 905	Fire Extinguisher,ABC,5 Lb. Loose Note: Quantity: Two (2) K Spec	\$102
<b>1000 -PATIENT HANDLING EQUIPMENT - STANDARD</b>		
I.		
I. 1	Cot fastener, Stryker #6371, rear hook wall mount, front antlers removable. (specify cot model)	
I. 1000		
<b>1100 -PAINT, BODY AND GRAPHICS - STANDARD</b>		
J.		
J. 1	Emblems, Leader front fenders, rear doors, No Smoking labels, ETC.	
<b>1100 -PAINT, BODY AND GRAPHICS - OPTIONS</b>		
J. 1100		
J. 1101	Add window tint to patient compartment OEM windows.	\$209

*By signing the following document you are entering into a sales agreement with Leader Industries to purchase the above vehicle/s.*

**Contract Total: \$74,055.00**

Customer Representative

Date:

Sales Representative

Date: